DART AEROSPACE LTD	Work Order :	19776
	Description:	<sup>'</sup> Inspection
	Approval :	
·		Page 1 of 1

Step	Location	Procedure ,	Ву	Date
1	PK	Remove from Stock Yes/No Return#		
		Qty Part Number Description Batch I D2667-2 19178: Sable 017610	12	703·10.10
2		Re-work/Inspection:		
	FP	Repruder Cont as per DS 1004	MI	Q -10. 91
	<i>à</i> 3	Inspect Rouder leat	2	07.10.21
	A SE	Nath Sept 3 July		
		indentify i stock	Ø -	3-11-210
}		· · · · · · · · · · · · · · · · · · ·		
3	PK	Identify & Stock:		
		Qty Part Number Description Batch		
		1 02667-2 5adole 1317810		13-11-26
			-	
	-			
	DC	/2,76 Close W/O	Sax	03-11-27
		Inspect Level 21	*	03,11,27